STATE OF LONDONDERRY DEPARTMENT OF PUBLIC WORKS



May 15, 2023

Presented by: Dave Wholley

Director of Public Works & Municipal Facilities

FACILITY COMMITTED







- ❖ Heavily invested in modernizing facilities over the past 20+ years
- However, what's missing? Perhaps Overlooked?
- Perhaps Council Resolution -Tax Payer Relief Act 0f 2020?
- ❖ HOWEVER, Perhaps now it's time to discuss the possibility of a DPW facility







MAIN AREAS OF CONCERN

- Site Conditions
- Material Storage
- Equipment Storage
- Facility Inadequacies
- Operational inefficiencies
- Employee Safety & Working Conditions



SITE CONDITIONS



- Muddy parking areas
- Muddy materials
- Muddy work areas
- Muddy mess











SITE CONDITIONS

- * Ice!!
- Unsmooth surfaces
- Slow runoffs
- Ponding water









MATERIAL STORAGE

- Grossly undersized sand/salt mix shed
- Small and tight salt sheds
- * All construction material uncovered
- Inadequate cold patch bin











MATERIAL STORAGE-TRAILERS



- ❖ Total of 9 storage structures
- In/on/under or around
- Unlit, not ventilated, unstable
- ❖ Impractical/unsafe











MATERIAL STORAGE-BUILDINGS



- Inadequate storage
- Improper storage
- Limited work surfaces
- Upstairs parts room
- Flammable materials



NO sprinkler/fire or ventilation systems













EQUIPMENT STORAGE – UNCOVERED

Year round outside – in sun, rain, snow, ice, mud, dust, bird waste, critters, rodents, etc.









EQUIPMENT STORAGE-LIMITED COVER





- Not immune to the elements
- ❖ Wildlife-critters, birds nest here









GARAGE INADEQUACIES

- No room for crimping machine
- Tight working quartersSpare parts and tools located in trailers












GARAGE INADEQACIES



- ❖ Built in 1971 (50+ years old)
- ❖ 40x80 (3200 sq. ft.) \$27K
- Limitations on work schedule
- ❖ Side by side tasks difficult
- Closes down garage to singular task
- Employees waiting on others welding/grinding/cutting









OPERATIONAL INEFFICIENCIES



- End up with an inferior product
- Clumps on screens and belts







- Wears on equipment hydraulics
- Places employees in the weather



OPERATIONAL INEFFICIENCIES





- Tight breakroom/training room
- Small locker room, limited locker space
- Move equipment to get at equipment
- Move supplies to get at supplies
- Limited back up power to garage











EMPLOYEE SAFETY & WORKING CONDITIONS



PUBLIC WORKS

All that we do, is in <u>response</u> to you!

FIRST RESPONDER













MOVING FORWARD

- ❖ Heavily invested in modernizing facilities over the past 20+ years
- ❖ However, what's missing? Perhaps Overlooked?
- Perhaps now it's time to discuss the possibility of a DPW facility

Request to authorize and conduct a Facility Master Plan Feasibility Study

- All previously mentioned items to be completely evaluated for lost efficiencies and inadequacies
- Determine appropriate square footage needs for each task needed and improved response times.
- Examine current location vs. alternate location within Londonderry
- Examine possibility for this facility to help with other community needs as follows:
 - Fleet management for all vehicles
 - Fuel farm for all departments-frees up space at Central Fire
 - · Relocate waste oil drop off-frees up space at Central Fire
 - Free up office and storage space at Town Hall
 - Potential for additional parking at Town Hall
 - Relocate drop off center to achieve year round access
 - Storage units for other departments-PD, FD, HR, Finance, TM, Etg.
 - Opportunity for GoGreen initiatives-solar panels/E.V. charging area
 - · Wash facility to improve longevity of costly equipment
 - List goes on and on-endless opportunities to solve long standing challenges

MODERN FACILITY



FLEET MANAGEMENT



FUEL FARM & SALT BARN



YEAR ROUND DROP OFF CENTER



GO GREEN!!!



BOUND BY THE LIMITATIONS OF NO FACILITY

If we had:

Vac/Jet truck

Street Sweeper

Mowers-lawn maintenance

Sidewalk machine

Hot box

Bulk liquid calcium/brine storage



We could perform:

Jetting of drain lines/culverts.

Sweep roads and MS4 compliance.

Hire seasonal summer help-mow cemeteries and other properties.

Provide winter maintenance for sidewalks.

Better and longer lasting repairs of pot holes.

Make better use of pre-wet systems resulting in enhanced salt operations

THANK YOU!!!

Questions/Comments?